

Powr-Flite®


PARTS LIST



**WARNING: OPERATOR MUST READ AND UNDERSTAND THIS MANUAL
COMPLETELY BEFORE OPERATING THIS EQUIPMENT.**

SCHEMATICS - PARTS LISTS

WW1000



SCHEMATICS - PARTS LISTS

No	Part No.	Qty	Description
1	7BF030	4	Nut 10-24 Nylon Insert Lock 18-8 SS
2		1	Wand Weldment
3	70068A	1	U-Type Handle
4	70100A	1	Nipple QD 1/8M Brass
5	70101A	1	Brass Nipple
6	70127A	1	Nipple QD 1/8F Male QD Brass
7	71130A	2	Nipple QD 1/8M Brass
8	71532A	4	Screw 4-40 1/4 SS
9	71700A	2	Retainer Clip 5/8
10	71817A	2	Rubber O-Ring
11	72140A	1	Screen Filter
12	72143A	1	Check Valve
13	72488A	AR	Brass Spray Tip Holder w/ Gasket
14	72489A	AR	Stainless Steel Spray Tip
15	72725A	AR	Nozzle Seal
16	7AG002	1	Bushing 1/4-1/8 NPT
17	7BF030	4	Nut 10-24 Nylon Insert Lock 18-8 SS
18	7BS001	5	Screw 10-24 x 1/2
19	7CU001	1	Screw 10-24 x 1
20	AA173VL	1	Trigger Valve
21	PC49	1	Brass Street Elbow 1/4 90 Degree
22	PX5	1	QD Fitting 1/ Male/Male
23	PX17	1	Brass Street Elbow 1/4 NPT 45 Degree
24	PX32	1	Brass Close Nipple 1/4
25	PX810	1	1000 PSI Wand
26	WWTB	2	Teflon Roller Bushing
27	WWH43	1	Teflon Hose
28	WWB	1	Roller Bracket Set of 2
29	WWTR	1	Roller
30	X8211	2	Screw 1/4-20 x 1
Not Shown	X2059	1	Manifold ONLY for WW1000-2
Not Shown	X2061	1	Manifold ONLY for WW1000

For warranty information go to www.Powr-Flite.com

Powr-Flite®

A Tacony Company

3101 Wichita Court • Fort Worth, TX 76140-1755
1-800-880-2913 • Fax: 1-817-551-0719